



## Service Bulletin: Variable Speed Heat Pump Muffler Failure

### From Nathan

The attached bulletin is to address leaks that are occurring in the line next to the muffler on some variable speed outdoor units.

If you have any questions at all please call me at the office or cellphone.

Thank you,

Nathan Walcott  
Field Service Representative



Cell: 309-846-2970  
Office: 309-820-0566

[DOWNLOAD BULLETIN](#)

