



## SERVICE BULLETIN

### O-Ring Deformation

We have received reports that deformation of the (4) O-rings on the condensate adapter are being found in the S9V2 furnace models.

Please download the [bulletin](#) for additional information, and contact me with any questions.



## APPLICATION BULLETIN

### Extended Pipe Length

With the introduction of the 17 SEER, 2 stage, 3 phase air conditioners and heat pumps, longer interconnecting refrigerant piping is now approved up to a total length of 150 feet with a vertical rise of 50 feet. These longer lengths and vertical rise can be accomplished using the specific pipe sizes and subcooling charts provided in the attached application bulletin. These longer lengths, using the specified pipe sizes are now also approved on all two stage, single compressor split system air conditioners and heat pumps.

Please download the [application bulletin](#) for more details, and contact me with any questions.

Thank you,

**Nathan Walcott**  
Field Service Representative

Cell: 309.846.2970

Office: 309.820.0566

[nathan.walcott@holtsupply.com](mailto:nathan.walcott@holtsupply.com)



